## Maintaining the coolant system vital to performance

The cooling system in a motor vehicle performs a vital function. It maintains a constant operating temperature in the engine and disposes of the excess heat.

The liquid coolant absorbs the heat in the cylinder block and circulates it into the radiator through the top radiator hose. Here it gets cooled down by air and passes back into the engine block through the lower radiator hose to absorb more heat and to begin the whole cycle again.

Some of the heat is used to circulate through the heater core to heat up the passenger compartment of the vehicle during the cold seasons.

**Cooling System Components** 

The components of a typical cooling system include a water pump, belt-driven from the crankshaft pulley, the radiator

fan, thermostat, upper and lower radiator hoses, the radiator, the radiator overflow tank, the heater core and the heater hoses.

What to check and when


Maintenance of the cooling system is simple, relatively inexpensive, yet very important. Cooling system failure often results from neglect and, apart from creating an emergency, it can cause serious damage to the engine. Weekly

Check coolant level. **Every Spring and Fall** 

Check for reasonable cleanliness of the liquid coolant.

Check condition and correct tension of the water pump drive belt (fan belt). Signs of cracks, peeling or glazing suggest an early replacement.

Check condition of the radiator and heater hoses.



Extreme softness or hardness, cracks or bulges signal an urgent need to replace them.

Carefully remove dead insects, trapped at the front of the radiator core, using a soft brush or a toothpick.

Check for presence of muddy sediments in the radiator neck. Caution: Never attempt to remove the radiator cap when the engine is hot. The coolant temperature can easily exceed 120 degrees celsius and only the radiator pressure cap keeps it from boiling over, violently.

Check hose clamps but do not overtighten. Damage to the hoses or fittings could result.

Check for any signs of coolant leakage.

Once every two years

Drain system. While you coolant still protects your system from freezing, its anticorrosion qualities are breaking

There usually is a pet-cock at the bottom of the radiator and a drain plug somewhere in the lower portion of the engine block. To speed up the draining process, the lower radiator hose can be removed at the radiator and pointed downward.

When all the coolant is drained, we are ready to reattach the lower hose to the radiator and to close the drain cock and the drain plug. The system should now be filled with water and the engine run at idling speed for about 20 minutes.

In about an hour after we shut the engine off, things should have cooled down enough to drain the system again. This should have disposed of most of the contamination present.

If there was any sign of cooling system leakage, a pressure check should be performed and the problem corrected, before fresh coolant is installed.

Refilling the system with glycol type coolant of recommended strength will follow the same procedure. Running the engine at idle for 20 minutes and topping up the system several times will allow sufficient time to purge all air pockets.

A routine check of the antifreeze strength every fall should be made without fail.







#### MEAT THAT DOES MORE THAN COMPETE

"IDEAL FOR B.B.Q." SIRLOIN T-BONE STEAK STEAK \$298 \$48

#### SUNSHINE FRESH PRODUCE

"Snowy White" MUSHROOMS

Product of Ont. or U.S.A.


"Fresh"

**ASPARAGUS** 


Product of U.S.A.



PHONE IN ORDERING 873-3963 \$3.00 CHARGE FOR DELIVERIES



Values Effective Monday, May 7 through Saturday, May 12, 1990



## PILLOW BACK SOFA, CHAIR




This contemporary suite is built for comfort, style and durability. Deep real comfort, adjustable backs, hardwood frame, no sag springs and nylon cover, means you get it all.

**REG.** 996 LESS TRADE 300

# 6 PC SOLID PINE

This solid pine grouping features a sofa, chair, rocker, coffee & 2 end tables. It comes in the natural wood finish and a herculon cover similar to suite illustrated.


**REG.** 699 LESS TRADE 300



This suite featuring solid oak accent front and a comfortable pillow back design gives that deep real comfort and 100% nylon cover means years of durability.

**REG. 1197** LESS TRADE 300

#### **DESIGNER SECTIONAL**



This comfortable suite features a loose cushion back and reversible seat cushions. A never wear nylon cover and hardwood frame means years of durability.

**REG. 777** LESS TRADE 300

#### TRADITIONAL SOFA, CHAIR



This suite features a never wear nylon acrylic cover with hardwood frame and no sag springs. To view this Canadian made set and 200 other suites, stop in today.

**REG. 1098** LESS TRADE 300



This stylish suite features a swivel rocker, your choice of floral print or solid colors. All hardwood frames and no sag springs and as usual fully warrantied.

**REG. 895** LESS TRADE 300

### SEE ONTARIO'S LARGEST CHESTERFIELD AND LEATHER GALLERY!

## CHESTERFIELD WHOLESALERS

BEHIND GUELPH AUTO MALL

120-126 MALCOLM RD. 763-4477

"A FAMILY BUSINESS BUILT ON SERVICE.

WE MAKE PEOPLE HAPPY."

CASH 'N CARRY PRICES ON ALL SALE ITEMS.

MON.-FRI. 9-9 SAT. 9-7 · VISA · MC · FINANCING

**FINE LINE MOTORS** MALCOLM RD. O.C.W.

ELMIRA RD. AUTOMALL HWY. #7

> **WE'RE ONLY MINUTES** AWAY, IN GUELPH

**HWY. #6** SOUTH