

No cost for expert advice on "How to Improve Vacant Property"

ROSENTHAL, MAYER & LEWIS,

Incorporated

*Builders of Hotels, Kitchenettes, Apartments,
Industrial Buildings*

*Insurance, Building Management
Real Estate Investment, Renting*

OUR references are clients for whom we have erected buildings. For those who will give us an opportunity to figure on any contemplated building, we will be pleased to make up sketches and financial setups—without cost. We have erected buildings of all kinds and types, and are therefore in a position to show you the actually completed buildings, making it unnecessary for you to visualize from blue prints only.

Telephone
State 8884

Suite 505-7
77 W. Washington Street
CHICAGO

Racer Meets Death



Lee Bible, auto race driver, who met his death at Daytona Beach, Florida, while trying to break a new auto speed record. His car skidded and plunged into a sand bank.

ART METAL WORK

THE SWEDISH ART METAL CO., Inc.
Gust. W. Lofgren, N. S. representative
653 Chicago Ave., Highland Park
Phone Highland Park 1799

Don't Suffer with Cough

or bronchitis when E.O.C. cough syrup is guaranteed to relieve coughs of long standing. Prevents pneumonia.

For Sale by
All Good Drug Stores

NOW IS TIME TO OVERHAUL THE CAR

Suggestions for Spring Which Motorists Will Find of Much Benefit

When a car has been driven through the winter there are a number of adjustments which should be made on it now if the owner would save more or less time and expense after the summer touring season begins, according to a bulletin issued by the mechanical first aid department of the Chicago Motor club.

Many manufacturers of automobiles recommend a heavier oil in the transmission case and differential in summer than in winter, the bulletin pointed out. Likewise, in many instances, the motor oil should be somewhat heavier in summer.

"The old grease should be removed from the front hubs and replaced with fresh lubricant," the bulletin set forth. "If the generator was adjusted to a higher charging rate in the winter, it should now be set back to the normal summer reading. The battery, which may have developed some defect as a result of difficult starting in winter, should be inspected and necessary repairs should be made.

Radiator Needs Attention

"After all possibility of a freezing temperature has passed, the anti-freeze solution should be removed from the radiator. This should be done after a long drive, as the sediment is then stirred up and much of it will come out with the solution. It is well to flush the radiator several times with water, so as to wash out all foreign matter. The grime that accumulates on leaf springs in the winter should be scraped off and the leaves oiled. After the oil has worked between the leaves, check the clips to see that they are tight.

A careful inspection of the tires will probably reveal some cuts.

"While one is repairing the ravages of winter, there are other tasks which should be attended to at this time, as well as at other frequent periods of the year. These comprise inspecting the brakes, checking the angle of the beam from the headlights, with a view of preventing glare; checking the spark plugs and cleaning or replacing those found faulty; draining any sediment from the gasoline and vacuum tanks and carburetor; cleaning and readjusting the points in the distributor housing, and many others. These jobs, if attended to periodically, will save the car owner many delays and in some instances a large repair bill later on."

However, a considerable number of people are willing to use their great mental powers at least to the extent of planning out their sports and pastimes.

BRING US YOUR LAUNDRY
AND CALL FOR IT. YOU WILL
SAVE 20%.

RELIABLE LAUNDRY
& DRY CLEANING COMPANY
618 N. Green Bay Rd. Highland Pk.

Statistics Show

That the average family of five provides a hospital case once in two years. So when you may have to go to the hospital you will be comforted to know that a place awaits you outside the din of city life where clean air and sunshine are abundant.

THE HIGHLAND PARK HOSPITAL

Telephone Highland Park 2550