Tung-Up

TOTAL SERVICE - INCLUDING PARTS * including ENGINE ANALYSIS

Most 4-cyl Parts* & Labor

* We Install: New Turbo Fire Spark Plugs; New Rotor; New Ignition Points† and New Condenser+ (+not required on Electronic Ignition).

We Test or Check: Compression of each cylinder; Battery; All ignition circuits; Ignition coil output; High-tension leads; Starter and circuitry; Alternator output; Voltage regulator; Distributor cap; Rotor gap voltage; Ballast resistor; Pick-up/reluctor gap; Heat riser valve; Manifold vacuum; Exhaust emission system; PCV valve; Air and fuel filters; All hoses and belts.

We Adjust: Timing; Carburetor; Carburetor linkage and Dwell Angle. And we clean the battery terminals.

Additional Parts and Installation Extra - if required.

Make your appointment for better car care today! CALL 884-1400



Installed Motomaster Shocks

Ride-O-Matic and Heavy-Duty Shocks are guaranteed as long as you own the car on which they are originally installed. Plus service

INSTALLED Ride-O-Matic

1" bore standard shocks with slightly firmer action than original equipment. Positive dampening action. Installed

INSTALLED Heavy-Duty

1/2" micro-finished rods for longer seal life. 25% more fluid than most standard shocks; large 11/16" piston. Installed.

Come in for a No-Charge Shock Absorber Inspection.

WHEEL

Remanufactured Parts Sample listings only—similar low prices on other makes.

Solenoid Switch

1973-76 Chev & Pontiac V8 350, 400 Orange Engines.

50 C25 Wexch. U full price

1971-76 Pinto & Bobcat, all engines. (no exchange) Full price . . \$3.99 to \$4.99 1971-76 Vega and Astre, all models. Exchange . \$5.50; Full price \$6.25

Starter Drive

1963-76 Chevrolet & Pontiac, all models, all engines.

exch. If full price

1971-76 Pinto & Bobcat, all models, all engine sizes . . . Exch. . \$5.39; Full . . . \$5.89 1971-76 Vega and Astre, all models, all engine sizes . . Exch. \$3.80; .Full . \$4.30

Starter Motor

1971-76 Vega and Astre, all engine sizes.

2895 3870 full price

1971-76 Chevrolet & Pontiac V8 350, 400 Orange Eng. Exchange \$26.49 to \$34.95 Full price \$31.99 to \$47.70 1971-76 Pinto, Bobcat, 4-cyl.

Exch. \$30.95; Full \$40.70

Regulator

1964-76 Ford & Mercury, all models, all engines . .

Q50 **Q**00 exch. If full price

1970-76 Dodge & Plymouth 6-cyl. & V8 (except 100 A) Exch. \$13.59; Full . \$14.09 1968-73 Datsun 510 models with 1600 engine. Exch. \$11.95; Full \$13.45

Alternator

1970-76 Dodge/Ply. 6-cyl, V8 (ex. AC & rear defogger) **995/1145**

exch. I full price

1971-76 Pinto & Bobcat, standard equipped (38-42A.) Exch. \$29.95; Full . \$37.45 1968-73 Datsun 510 with 1600 eng. Exch. . . \$47.95;

Full price \$60.70

OCTOBER SAVINGS INSTALLED **CUSTOM FIT ENGINE HEATERS**


CLAMP INTO FROST PLUG HOLE MOST CANADIAN BUILT CARS. CGE CALROD, ELEMENT (SEE SAMPLE LISTINGS BELOW)

ALL CANADIAN BUILT 6 CYL. CHEV, FORD, VALIANT, MAVERICK, ETC. REG. 17.35

ALL CANADIAN BUILT 8 CYL. CHEV, FORD, PONTIAC DODGE, PLYMOUTH, ETC. REG. 122.95

MOTORMASTER ENGINE HEATER 800 WAT 120 VOLT, THERMOSTATI CONTROLLED MOUNTS INTO HEATER HOSE SYSTEM. EASY COLD WEATHER STARTING FOR ALL IMPORTS. DATSUN. TOYOTA, VOLVO, AUSTIN,

REG. 126.35



Water Pump

Water Pumps for most

Sample: 1961-1976 Dodge & Plymouth 6-cyl. Exchange

Molded Radiator Hose

(192°F); high (180°F) and

low (160°F). Each, from .

2. Available for most popular makes of cars 159 Q49 and trucks. Each, from ...


. Standard replace-

ment for most popular N. American makes. Each

Cash Bonus

parts

Extra Savings! Coupons on all



Remanufactured

Q99 2249 Radiator Pressure Caps


other makes, exchange

Model-for-model exchange basis only. Trade-in unit must be complete with no visible cracks.

One-Stop-Shop for Parts and **Total Service**

Everything for your car, including fully guaranteed.

ALIGNMENT SPECIAL! **4 DAYS ONLY** OCTOBER 26 - 29



All Canadian and imported

passenger cars,

½ ton trucks and

including Suspension Check

> Compare our **Total Service**

Set toe, caster, camber Adjust steering gear

Centre steering wheel


Generally inspect steering Adjust wheel bearings Check wheel bearing noise

Inspect front and rear suspension Adjust torsion bar

☑ Correct toe change Check tire pressure

Parts and Installation extra

CALL 884-1400 FOR YOUR APPOINTMENT



Motomaster Front End Parts Idler Arms Tie Rod Ends **Ball Joints** 1967-73 full-size Dodge 1965-77 full-size Ford,

1971-76 full-size Chev and Canadian Pontiac

Merc, Meteor, Upper

and Plymouth.

Sample Listings Only — We can supply for most popular makes and models



10288 YONGE ST. - RICHMOND HILL 884-1196

the experts who know how to care for it, is under one roof at your Canadian Tire Auto Centre. You can trust them for all your service needs. And parts and labor are