

VI A fine view of the rolling hills of Northumberland County. When Mr. Dallison took this picture, he stood on the pipe at the top of the hill seen in the previous picture, and faced east. The hill in the background, is just over 3 miles away.



VII A large hull dozer moving the buffing machine along the pipe line. This machine was used to scrape rust off the pipe-line by a series of rapidly revolving steel brushes, and then applying the first of several coatings of tar used on the pipe-line. This machine is the next to last one to work along the pipe-line.

